

Block or Band Change

Price includes labor and circuit board required to change the block/band.
Not all blocks/bands available. Discontinued products have limited boards/parts available.
For a quote or questions, contact service.repair@lectrosonics.com or call 1-800-821-1121.
Prices effective April 15, 2024

Price	Block Change (printed circuit board assemblies included in pricing)
509.00	HHA
474.00	HMA
771.00	IFBT4 (UHF ONLY)
760.00	LMB
687.00	LR
537.00	LT
682.00	Octopack
786.00	R400A
578.00	SMWB / SMDWB
570.00	SMV / SMQV
849.00	SSM
809.00	SR/SRA/SRB
999.00	SRC
421.00	UCR100
497.00	UCR401
1034.00	UCR411A
1455.00	VRM2
393.00	VRS/E01 (Limited Availability)
508.00	VRT2
570.00	WM
300.00	Distribution Amplifier Block Change or Wide Band Upgrade [UMC200D, UMC16, UDM6(S)(pair), UDM5(S)(pair), UFM50, UFM230] Parts not included in price.

Products are eligible for block change only within 7 years from the date of manufacture/original sale with the exception distribution amplifiers.

Housings may be marred when removing serial number plates or during the engraving process. Units with block information engraved on the housing will have a strikethrough line across the old frequency information and the new frequency data engraved next to it. Customers may have housings replaced at their request at an additional cost (contact the Repair Department for housing pricing).

All products will be updated with the latest firmware and specifications to be in compliance with current FCC regulations.

Any additional parts necessary to repair the item to proper working order will be added to the price shown.